

# Inspection Photos

API: 071-09420

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/19/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09420 | Date: 4/19/2021

## Inspection Photos



**Photo 1.** The pig launcher receiver remains along the access road which needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09420 | Date: 4/19/2021



## Inspection Photos



**Photo 2.** A metal flowline box remains along the access road which needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09420 | Date: 4/19/2021



## Inspection Photos



**Photo 3.** There is a pipe riser that remains along the main access road at Lat/Long:37.26190,-104.98726. This was previously observed and has not been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09420 | Date: 4/19/2021



## Inspection Photos



**Photo 4.** Facing along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09420 | Date: 4/19/2021



## Inspection Photos



**Photo 5.** Facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09420 | Date: 4/19/2021



## Inspection Photos



**Photo 6.** Facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09420 | Date: 4/19/2021