

# Inspection Photos

API: 071-08890

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/19/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08890 | Date: 4/19/2021

## Inspection Photos



**Photo 1.** There was vehicle rutting along areas of the main road coming from wet canyon. Areas of rutting need to be maintained and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08890 | Date: 4/19/2021

## Inspection Photos



**Photo 2.** Facing northwest along the main road near the launcher/receiver. Gravel has been graded off the road in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08890 | Date: 4/19/2021

## Inspection Photos



**Photo 3.** Facing southeast along the access road There is grading disturbance which needs to be reclaimed near the pig launcher.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08890 | Date: 4/19/2021

## Inspection Photos



**Photo 4.** This graded disturbed area along the access road is susceptible to erosion and needs to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08890 | Date: 4/19/2021

## Inspection Photos



**Photo 4.** Facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08890 | Date: 4/19/2021

## Inspection Photos



**Photo 6.** Well sign posted at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08890 | Date: 4/19/2021