

# Inspection Photos

API: 071-08451

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/19/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08451 | Date: 4/19/2021

## Inspection Photos



**Photo 1.** Facing south toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08451 | Date: 4/19/2021



## Inspection Photos



**Photo 2.** There is a white salt like substance spilled on the ground at the north side of the location which needs to be cleaned up.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08451 | Date: 4/19/2021



## Inspection Photos



**Photo 3.** Facing south at center of the location. There is oil stained soil shown at red arrow which needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08451 | Date: 4/19/2021



## Inspection Photos



**Photo 4.** There was a road built to the south of the location. The road is causing disturbance of the interim reclamation. Vehicle access needs to be prevented.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08451 | Date: 4/19/2021



## Inspection Photos



**Photo 5.** There is vehicle rutting and disturbance that occurred which needs to be repaired and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08451 | Date: 4/19/2021