

Inspection Photos

API: 071-08730

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/19/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08730 | Date: 4/19/2021

Inspection Photos



Photo 1. Facing southwest toward the access road. Recontouring and reclamation has been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08730 | Date: 4/19/2021

Inspection Photos



Photo 2. Facing southwest toward the location. The location has been recontoured back to pre-existing conditions.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08730 | Date: 4/19/2021

Inspection Photos



Photo 3. Facing south at the location. Soils are bare and susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08730 | Date: 4/19/2021

Inspection Photos



Photo 4. There are signs of riling beginning to occur. BMPs will likely need to be installed to prevent erosion. (E.G. Hydromulch, erosion blanket, wattles, ect.)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08730 | Date: 4/19/2021

Inspection Photos



Photo 5. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08730 | Date: 4/19/2021

Inspection Photos



Photo 6. There is some germination beginning to occur. Operator will need to monitor vegetation establishment and stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08730 | Date: 4/19/2021