

Inspection Photos
Location Name: Federal 2-26
Location ID: 313020



Photo 1. Overview of location taken at entrance facing southeast.



Photo 2. Wellhead sign incomplete/inaccurate. No bradenhead access apparent.



Inspection Photos
Location Name: Federal 2-26
Location ID: 313020



Photo 3. Battery sign incomplete/inaccurate.



Photo 4. Tank label incomplete/inaccurate.

Inspection Photos
Location Name: Federal 2-26
Location ID: 313020



Photo 5. Animal burrows in berm.




Photo 6. Gas meter not calibrated annually.