

Inspection Photos
Location Name: Hebron 078 S18 Pad
Location ID: 414127



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Signs at entrance incomplete/inaccurate.



Inspection Photos
Location Name: Hebron 078 S18 Pad
Location ID: 414127



Photo 3. Sign at entrance incomplete/inaccurate.



Photo 4. Wellhead sign incomplete/inaccurate.



Inspection Photos
Location Name: Hebron 078 S18 Pad
Location ID: 414127



Photo 5. Wellhead sign incomplete/inaccurate.



Photo 6. Wellhead sign incomplete/inaccurate.



Inspection Photos
Location Name: Hebron 078 S18 Pad
Location ID: 414127



Photo 7. Wellhead sign incomplete/inaccurate.



Photo 8. Tank label incomplete/inaccurate.



Inspection Photos
Location Name: Hebron 0780 S18 Pad
Location ID: 414127



Photo 9. Stained soil at wellhead.



Photo 10. Stained soil at wellhead.

