

Inspection Photos
Location Name: Grant Take Battery
Location ID: 446484



Photo 1: Location Sign



Photo 2: Buried concrete produced water vessel on east side of compressor building.



Inspection Photos
Location Name: Grant Take Battery
Location ID: 446484



Photo 3: Meter shed and compressor building.



Photo 4: Eastern excavation, viewed from southeast corner.



Inspection Photos
Location Name: Grant Take Battery
Location ID: 446484



Photo 5: Eastern excavation viewed from northwest corner.



Photo 6: Eastern excavation viewed from southwest corner.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Grant Take Battery
Location ID: 446484



Photo 7: Unused piping on location.



Photo 8: Western excavation, viewed from west side.



Inspection Photos
Location Name: Grant Take Battery
Location ID: 446484



Photo 9: Removed fiberglass vessel on location.



Photo 10: Groundwater in western excavation.



Inspection Photos
Location Name: Grant Take Battery
Location ID: 446484



Photo 11: Groundwater in eastern excavation.



Photo 12: Unused equipment: AST and ancillary piping on location.

Inspection Photos
Location Name: Grant Take Battery
Location ID: 446484



Photo 13: Unused AST on location



Photo 14: Portable water tank on location, staged on southern side of excavation.

