

FORM
INSPRev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2021

Submitted Date:

04/21/2021

Document Number:

698702984

FIELD INSPECTION FORM

Loc ID 333063 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292971	WELL	SI	07/01/2020	GW	123-26429	NOFFSINGER F 2-4	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 292971 Type: WELL API Number: 123-26429 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On (4/21/21) at approximately 1, Inspector (Abe Serna), Conducted an on-site inspection at (Noffsinger F 2-4) (Noble Energy), at (API # 123-26429) in (Weld County) Colorado. While there, I observed a (SI Well) During this inspection no compliance issues were observed. No follow up on this site inspection needs to be conducted. This is a summary of inspection report.</p>	sernaa	04/21/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698702985	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5410019