

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 32-23

Location ID: 426123



Photo #3577 from entrance to location.




Photo #3578 location lacks stabilization.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 32-23

Location ID: 426123



Photo #3095 from inspection #699802728 conducted on 3/8/21.



Photo #3579 location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 32-23

Location ID: 426123



Photo #3097 from inspection #699802728 conducted on 3/8/21.



Photo #3580 No form of tracking BMP at entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 32-23

Location ID: 426123



Photo #3098 from inspection #699802728 conducted on 3/8/21.



Photo #3581 No tank battery sign located at the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources