

Inspection Photos

4/16/2021

Operator: TEP ROCKY MOUNTAIN LLC #
96850

Location ID: 383332
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 383332



Photo 1: Photo taken from the interim areas on the southeast end of the Location, facing southeast. Photo shows desirable perennial vegetative establishment is not progressing towards 1003 reclamation standards; vegetation predominantly undesirable weedy annual plant species such as cheat grass



Photo 2: See comments under photo 1.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 383332



Photo 3: Photo taken from the interim areas on the southeast end of the Location, facing northeast. Photo shows desirable perennial vegetative establishment is not progressing towards 1003 reclamation standards; vegetation predominantly undesirable weedy annual plant species such as cheat grass



Photo 4: Photo taken from the interim areas on the northeast end of the Location, facing south. Photo shows desirable perennial vegetative establishment is not progressing towards 1003 reclamation standards; vegetation predominantly undesirable weedy annual plant species such as cheat grass

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 383332



Photo 5: Photo taken from the interim areas on the north end of the Location, facing south. Photo shows desirable perennial vegetative establishment is not progressing towards 1003 reclamation standards; green vegetation observed in photo is predominantly undesirable weedy annual plant species such as cheat grass



Photo 6: Continued from photo 5. Photo shows vegetation observed is predominantly undesirable weedy annual plant species such as cheat grass

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 383332




Photo 7: Photo taken from the interim areas on the northwest end of the Location, facing southwest. Photo shows desirable perennial vegetative establishment is not progressing towards 1003 reclamation standards; green vegetation observed in photo is predominantly undesirable weedy annual plant species such as cheat grass



Photo 8: Continued from photo 7. Photo shows vegetation observed is predominantly undesirable weedy annual plant species such as cheat grass

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 383332



Photo 9: Continued from photo 7. Photo shows vegetation observed is predominantly undesirable weedy annual plant species such as cheat grass



Photo 10: Continued from photo 7. Photo shows vegetation observed is predominantly undesirable weedy annual plant species such as cheat grass



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources