

Inspection Photos
Location Name: 70 Ranch State BB18-655 Multi
Location ID: 441841



Photo #1 Wells



Photo #2 Location

Inspection Photos
Location Name: 70 Ranch State BB18-655 Multi
Location ID: 441841



Photo #3 No mechanical conditions or oily waste



Photo #4 Repaired berm

Inspection Photos
Location Name: 70 Ranch State BB18-655 Multi
Location ID: 441841



Photo #5 Removed unused equipment



Photo #6 Repaired berm

Inspection Photos
Location Name: 70 Ranch State BB18-655 Multi
Location ID: 441841



Photo #7 Removed unused equipment



Photo #8 Removed unused equipment