

Inspection Photos
Location Name: 70 Ranch State BB18-689 Pad
Location ID: 441834



Photo #1 Wells

Photo #2 Removed unused equipment

Inspection Photos
Location Name: 70 Ranch State BB18-689 Pad
Location ID: 441834




Photo #3 Removed Unused Equipment

Photo #4 Removed Stained soil