

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2021

Submitted Date:

04/23/2021

Document Number:

699103440

FIELD INSPECTION FORM

Loc ID 441834 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections
Evins, Bret		bret.evins@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441833	WELL	SI	11/01/2020	OW	123-41529	70 Ranch State BB18-681	SI
441835	WELL	SI	10/01/2020	OW	123-41530	70 Ranch State BB18-689	SI

General Comment:

[This is a follow up to FIRR #402667710. All CA's have been corrected.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 441833 Type: WELL API Number: 123-41529 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/30/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Will need updated annual bradenhead test on file after 4-30-21

Corrective Action: _____ Date: _____

Facility ID: 441835 Type: WELL API Number: 123-41530 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/30/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Will need updated annual bradenhead test on file after 4-30-21

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 4/23/21 at approximately 1020hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR document #402667710 at 70 Ranch State BB18-689 Pad of Noble Energy, at Location ID # 441834 in Weld County, Colorado. During this inspection the compliance issue has been corrected to comply with COGCC rules. See attached photos. This is a summary of inspection report.</p>	burnsa	04/23/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103441	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411504