

Inspection Photos
Robert G Berge #2
Remediation Project No. 15743/Spill ID 476918 (CL)



**Photo 1 – Spill area. Excavation has been backfilled
disturbed surfaces have been ripped.**



**Photo 2 – Spill area. Excavation has been backfilled
disturbed surfaces have been ripped.**

Inspection Photos
Robert G Berge #2
Remediation Project No. 15743/Spill ID 476918 (CL)



Photo 3 – Repaired ditch wall



Photo 4 – Spill area access road; road has been ripped.