

Inspection Photos
Location Name: ORR-66N64W /3SESE
Location #: 305790



Colorado Oil & Gas Conservation Commission
Weld
+40.509319, -104.528465
23° NE
22-Apr-2021 15:22

Photo #1

Orr 44-3 (05-123-23483) Wellsite
Plugged & Abandoned | PA
~ 20 yds.



Colorado Oil & Gas Conservation Commission
Weld
+40.511010, -104.530243
6° N
22-Apr-2021 15:16

Photo #2

Rogers 33-3, USX A03-09D, Egge USX A03-11D,
Orr USX A03-15D Battery site
Inactive | Shut-down.
Formerly served:
Orr 44-3
Plugged & Abandoned | PA

Inspection Photos
Location Name: ORR-66N64W /3SESE
Location #: 305790



Photo #3

**Rogers 33-3, USX A03-09D, Egge USX A03-11D,
Orr USX A03-15D Battery site**
Inactive | Shut-down.
Battery sign