

Inspection Photos

4/23/2021

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 315713

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315713



20210423

Photo 1: Photo taken from west end of the Location, facing north. Photo shows area where the tank was Location. Photo shows final reclamation activities including, but not limited to, compaction alleviation, recontouring/regrading and revegetation activities have not been conducted on Location and access road; photo also shows that the containment berm and area where tank was located remains evident.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315713



Photo 2: Photo taken from the west end of the Location, facing east. See comments under photo 1.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315713



Photo 3: Photo taken from area where tank was Located, on the northwest end of the Location. See comments under photo 1. .

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315713



Photo 4: Photo taken from the east end of the Location, facing west. See comments under photo 1.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315713



Photo 5: Photo taken from the access road, facing west. See comments under photo 1.