

TEP ROCKY MOUNTAIN LLC
PA-66S95W 34SENW
Location # 324189



TEP ROCKY MOUNTAIN LLC
PA-66S95W 34SENW
Location # 324189



Weed debris cleared from access road.



access road is soft loose uncompact soil

TEP ROCKY MOUNTAIN LLC
PA-66S95W 34SENW
Location # 324189



Soft sediment in ditch is riling.



access road is soft loose uncompact soil

TEP ROCKY MOUNTAIN LLC
PA-66S95W 34SENW
Location # 324189



access road is soft loose uncompact soil



Rutted main road.

TEP ROCKY MOUNTAIN LLC
PA-66S95W 34SENW
Location # 324189



Sediment in ditch on main road.



Ditch needs maintained.