

Inspection Photos
Location Name: Calvary USX EE 29-04D Tank
Location ID: 306408



Photo 1: Wellhead Sign




Photo 2: Wellhead



Inspection Photos
Location Name: Calvary USX EE 29-04D Tank
Location ID: 306408



Photo 3: Tank Battery



Photo 4: Unused Equipment

