

# Inspection Photos

4/23/2021

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 314804

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314804



**Photo 1:** Photo taken from the west end of the Location. Photo shows that the gully erosion has been repaired, and control measures implemented.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314804



**Photo 2:** Photo taken from the west end of the production area, facing northeast. Photo shows control measures to stabilize the production areas, and prevent off-site sediment transport during wet conditions are missing or insufficient.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314804



**Photo 3:** Photo taken from the west end of the production area, facing southeast. Photo shows control measures to stabilize the production areas, and prevent off-site sediment transport during wet conditions are missing or insufficient.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314804



**Photo 4:** Photo taken from the southeast end of the production area, facing north. Photo shows control measures to stabilize the production areas, and prevent off-site sediment transport during wet conditions are missing or insufficient.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314804



**Photo 5** Photo taken from the access road entrance, facing north. Photo shows control measures to stabilize the production areas, and prevent off-site sediment transport during wet conditions are missing or insufficient.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314804



**Photo 6:** Photo taken from the access road entrance, facing west. Photo shows control measures to stabilize the production areas, and prevent off-site sediment transport during wet conditions are missing or insufficient.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314804




**Photo 7:** Photo taken from the access road entrance, facing south. Photo shows control measures to stabilize the production areas, and prevent off-site sediment transport during wet conditions are missing or insufficient.

## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 314804



**Photo 8:** Photo taken from the access, facing south. Photo shows control measures to stabilize the production areas, and prevent off-site sediment transport during wet conditions are missing or insufficient.

