

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402671094

Date Received:

04/26/2021

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

479834

**SPILL/RELEASE REPORT (SUPPLEMENTAL)**

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

**OPERATOR INFORMATION**

Name of Operator: <u>KP KAUFFMAN COMPANY INC</u>	Operator No: <u>46290</u>	<b>Phone Numbers</b>
Address: <u>1675 BROADWAY, STE 2800</u>		Phone: <u>(303) 8254822</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>( )</u>
Contact Person: <u>Jeff Rickard</u>		Email: <u>jrnickard@kpk.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

**INITIAL SPILL/RELEASE REPORT**

Initial Spill/Release Report Doc# 402661841

Initial Report Date: 04/18/2021 Date of Discovery: 04/17/2021 Spill Type: Recent Spill

**Spill/Release Point Location:**

QTRQTR NENW SEC 34 TWP 2N RNG 67W MERIDIAN 6

Latitude: 40.099319 Longitude: -104.880525

Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

**Reference Location:**

Facility Type: OFF-LOCATION FLOWLINE  Facility/Location ID No \_\_\_\_\_  
 Spill/Release Point Name: Suckla Farms E #2 Flowline  Well API No. (Only if the reference facility is well) 05- -  
 No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=1 and <5 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=1 and <5

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

Has the subject Spill/Release been controlled at the time of reporting? \_\_\_\_\_

**Land Use:**

Current Land Use: CROP LAND Other(Specify): \_\_\_\_\_

Weather Condition: Sunny, Cool

Surface Owner: FEE Other(Specify): \_\_\_\_\_

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Flowline failed at location where third party midstream operator recently installed line. Visual observations at release location show significant soil settling where release occurred as a result of the third party pipeline installation. KPK immediately shut in associated well operations to prevent further release. A vac truck was brought in to remove liquids at surface. Light excavation equipment scraped surface impacts in preparation for larger excavation activities.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

### OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
4/17/2021	Weld County/LEPC	Weld County OEM	-	Notification of Release, On-line spil report
4/17/2021	Landowner	Spurling	-	Notification of Release

### REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_  
Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_  
Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_

Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)  
Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_  
Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_  
Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_  
Was there damage during excavation? \_\_\_\_\_  
Was CO 811 notified prior to excavation? \_\_\_\_\_

Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_

Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

- The presence of free product or hydrocarbon sheen Surface Water
- The presence of free product or hydrocarbon sheen on Groundwater
- The presence of contaminated soil in contact with Groundwater
- The presence of contaminated soil in contact with Surface water

Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.

Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.

Areas offsite of Oil & Gas Location     Off-Location Flowline right of way

Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.

Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

### SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date:	04/26/2021		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown	
OIL	_____	_____	<input checked="" type="checkbox"/>	
CONDENSATE	_____	_____	<input checked="" type="checkbox"/>	
PRODUCED WATER	_____	_____	<input checked="" type="checkbox"/>	
DRILLING FLUID	_____ 0	_____ 0	<input type="checkbox"/>	
FLOW BACK FLUID	_____ 0	_____ 0	<input type="checkbox"/>	
OTHER E&P WASTE	_____ 0	_____ 0	<input type="checkbox"/>	
specify: _____				
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>				
<i>Secondary containment, including walls &amp; floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>				
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>				
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature				
Surface Area Impacted: Length of Impact (feet): _____		Width of Impact (feet): _____		
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____		
How was extent determined?				
Extent is unknow at ths time.				
Soil/Geology Description:				
SC				
Depth to Groundwater (feet BGS) <u>20</u>		Number Water Wells within 1/2 mile radius: <u>7</u>		
If less than 1 mile, distance in feet to nearest		Water Well <u>639</u> None <input type="checkbox"/>	Surface Water <u>380</u> None <input type="checkbox"/>	
		Wetlands _____ None <input checked="" type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>	
		Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building <u>1251</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:				
This form is being submitted to meet the requirements to submit a supplemental Form 19 within the specified timeline from the initial Form 19 defined by rule. The root cause hypothesis stated in the initial Form 19 remains unchanged at this time, KPK still believes the fiberglass line failed due to settling subsoil and over burden from a directly adjacent 3rd party gathering line install. Currently (as of 04/26/21) the line is being potholed by a vac truck for exact location before excavation begins (photo attached). KPK has no estimate of the volume of spilled fluid or impacted soil at this time, once a reasonable estimate is able to be made, KPK will include those volumes on a subsequent 19. Excavation and disposal of the impacted soil will start immediately after all utilities in the area have been located by vac truck. KPK will submit a Request for Closure Form 19 as soon as impacted soil cleanup is completed and confirmed by discreet soil sampling to Table 915-1 standards.				

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

- Basis for Closure:
- Corrective Actions Completed (documentation attached, check all that apply)
    - Horizontal and Vertical extents of impacts have been delineated.
    - Documentation of compliance with Table 915-1 is attached.
    - All E&P Waste has been properly treated or disposed.
  - Work proceeding under an approved Form 27 (Rule 912.c).  
Form 27 Remediation Project No: \_\_\_\_\_
  - SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

**OPERATOR COMMENTS:**

This form is being submitted to meet the requirements to submit a supplemental Form 19 within the specified timeline from the initial Form 19 defined by rule. The root cause hypothesis stated in the initial Form 19 remains unchanged at this time, KPK still believes the fiberglass line failed due to settling subsoil and over burden from a directly adjacent 3rd party gathering line install. Currently (as of 04/26/21) the line is being potholed by a vac truck for exact location before excavation begins (photo attached). KPK has no estimate of the volume of spilled fluid or impacted soil at this time, once a reasonable estimate is able to be made, KPK will include those volumes on a subsequent 19. Excavation and disposal of the impacted soil will start immediately after all utilities in the area have been located by vac truck. KPK will submit a Request for Closure Form 19 as soon as impacted soil cleanup is completed and confirmed by discreet soil sampling to Table 915 -1 standards.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Jeff Rickard  
 Title: Regulatory Date: 04/26/2021 Email: jrickard@kpk.com

<u>COA Type</u>	<u>Description</u>

### Attachment List

<u>Att Doc Num</u>	<u>Name</u>
402671109	PHOTO DOCUMENTATION
402671110	MAP
402671111	TOPOGRAPHIC MAP

Total Attach: 3 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)