

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/26/2021

Submitted Date:

04/26/2021

Document Number:

697003556

**FIELD INSPECTION FORM**
 Loc ID 330222 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name | Phone | Email                         | Comment |
|--------------|-------|-------------------------------|---------|
| ,            |       | cogccinspections@anadarko.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 250850      | WELL | PR     | 02/01/2020  | OW         | 123-18653 | Held 12-1418  | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | WELLHEAD     |       |  |
| Comment:           | Chain link   |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           | Chain link   |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           | Chain link   |       |  |
| Corrective Action: |              | Date: |  |

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| <b>Equipment:</b>         |   |       | corrective date |
| Type: Bradenhead          | # 1                                     |       |                 |
| Comment:                  | Bradenhead valve is exposed at surface. |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Bird Protectors     | # 2                                     |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Ancillary equipment | # 3                                     |       |                 |

|                                   |     |  |  |       |  |
|-----------------------------------|-----|--|--|-------|--|
| Comment:                          |     | Automation array and two ECD scrubbers |  | Date: |  |
| Corrective Action:                |     |  |  | Date: |  |
| Type: Emission Control Device     | # 1 |  |  |       |  |
| Comment:                          |     |  |  | Date: |  |
| Corrective Action:                |     |  |  | Date: |  |
| Type: Gas Meter Run               | # 1 |  |  |       |  |
| Comment:                          |     | Calibration card is current            |  | Date: |  |
| Corrective Action:                |     |  |  | Date: |  |
| Type: Flow Line                   | # 1 |  |  |       |  |
| Comment:                          |     |  |  | Date: |  |
| Corrective Action:                |     |  |  | Date: |  |
| Type: Plunger Lift                | # 1 |  |  |       |  |
| Comment:                          |     |  |  | Date: |  |
| Corrective Action:                |     |  |  | Date: |  |
| Type: Horizontal Heated Separator | # 1 |  |  |       |  |
| Comment:                          |     |  |  | Date: |  |
| Corrective Action:                |     |  |  | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity                         | Type           | Tank ID | SE GPS |
|--------------------|---|----------------------------------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 100 BBLS                         | PBV FIBERGLASS |         | ,      |
| Comment:           |   | Produced water vault is anchored |                |         |        |
| Corrective Action: |   |                                  |                | Date:   |        |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 1 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           | Date:   |        |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Other (Type)       |          |                     |                     |             |       |
| <b>Berms</b>       |          |                     |                     |             |       |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |
| <b>Venting:</b>    |          |                     |                     |             |       |
| Yes/No             | NO       |                     |                     |             |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |
| <b>Flaring:</b>    |          |                     |                     |             |       |
| Type               |          |                     |                     |             |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Inspected Facilities**Facility ID: 250850 Type: WELL API Number: 123-18653 Status: PR Insp. Status: SI**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 05/22/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 19 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 1

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 697003557    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413268">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413268</a> |