

Inspection Photos
Location Name: Charles C. Bell unit 1
Location ID: 317754



Photo 1 Well site is not accessible with vehicle, gates are stuck inside of cattle guard. Gates open enough to walk in.



Photo 2 WH sign faded.

Inspection Photos
Location Name: Charles C. Bell unit 1
Location ID: 317754



Photo 3 WH



Photo 4 WH valves are closed

Inspection Photos
Location Name: Charles C. Bell unit 1
Location ID: 317754



Photo 5 pump jack



Photo 6 ancillary equipment

Inspection Photos
Location Name: Charles C. Bell unit 1
Location ID: 317754



Photo 7 Electric panel is shut off.



Photo 8 TB sign

Inspection Photos
Location Name: Charles C. Bell unit 1
Location ID: 317754



Photo 9 TB

Photo 10 Flow line manifold

Inspection Photos
Location Name: Charles C. Bell unit 1
Location ID: 317754



Photo 11 Horizontal Heated Separator



Photo 12 Gas meter run