

Inspection Photos  
Location Name: Margaret Twombly B3  
Location ID: 332957



Photo 1 WH sign fell to the ground is faded needs replaced .

Photo 2 WH .

**Inspection Photos**  
**Location Name: Margaret Twombly B3**  
**Location ID: 332957**



**Photo 3 Valves are closed on WH flow lines.**

**Photo 4 Dead weeds around location.**

**Inspection Photos**  
**Location Name: Margaret Twombly B3**  
**Location ID: 332957**



**Photo 5 Dead weeds around location.**

**Photo 6 Dead weeds around location.**

**Inspection Photos**  
**Location Name: Margaret Twombly B3**  
**Location ID: 332957**



**Photo 7 ancillary equipment.**

**Photo 8 no meter on meter box.**

**Inspection Photos**  
**Location Name: Margaret Twombly B3**  
**Location ID: 332957**



**Photo 9 electric panel is shut off.**

**Photo 10 antenna pole laid over leaning on fencing.**