

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/15/2021

Submitted Date:

04/27/2021

Document Number:

688310381

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
316997 _____ Sherman, Susan _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10691
Name of Operator: PHOENIX RESOURCES LLC
Address: 5566 S SYCAMORE STREET
City: LITTLETON State: CO Zip: 80120

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Heffner, Taylor	303-219-3362	theffner@phxresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234270	WELL	TA	08/01/2020	OW	121-06377	BLAKE 1	PA

General Comment:

PA Inspection, Day 2

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 234270 Type: WELL API Number: 121-06377 Status: TA Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Bohler Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 2230', 147' Cement Volume (sx): 50, 50

Good Return During Job: YES Cement Type: G

Comment: 4/15/2021
Rig set CICR on turing at 2230' and pumped 50 sxs G cement/neat. 15.4 ppg
Pumped 50 sxs at surface with cement returns to tank

Corrective Action: _____ Date: _____

Workover

Comment: Bohler Rig/Chris

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688310428	Phoenix Resources Blake 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413952