

Inspection Photos
Location Name: Bangert 42-19
Location ID: 317922



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Bangert 42-19
Location ID: 317922



Photo 3 Pump Jack



Photo 4 dead weeds around ancillary equipment

Inspection Photos
Location Name: Bangert 42-19
Location ID: 317922



Photo 5 Stained soil by BH.



Photo 6 Stained soil in PJ base.

Inspection Photos
Location Name: Bangert 42-19
Location ID: 317922



Photo 7 Fencing in disrepair, posts broken.



Photo 8 Horizontal Heated Separator

Inspection Photos
Location Name: Bangert 42-19
Location ID: 317922



Photo 9 TB sign

Photo 10 TB



Inspection Photos
Location Name: Bangert 42-19
Location ID: 317922



Photo 11 Gas Meter Run