

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2021

Submitted Date:

04/21/2021

Document Number:

699103413**FIELD INSPECTION FORM**Loc ID 456625 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 456964 | WELL | PR | 04/01/2019 | OW | 123-47683 | Independence D30-765 | PR |
| 456965 | WELL | PR | 04/26/2019 | OW | 123-47684 | Independence D30-777 | PR |
| 456967 | WELL | PR | 04/26/2019 | OW | 123-47685 | Independence D30-770 | PR |
| 456969 | WELL | PR | 04/25/2019 | OW | 123-47687 | Independence State D30-784 | PR |
| 456972 | WELL | PR | 04/26/2019 | OW | 123-47690 | Independence D30-758 | PR |
| 459321 | WELL | DG | 10/05/2020 | | 123-48804 | Independence D18-759 | DG |
| 459322 | WELL | DG | 10/09/2020 | | 123-48805 | Independence D18-767 | DG |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|--|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Wells that are in drilling status will need a well sign. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|-------|------------|
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | Trash in multiple locations needs to be removed for good housekeeping. See attached photos. | | |
| Corrective Action: | Comply with Rule 606 | Date: | 04/30/2021 |

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|---------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 7 | | |
| Comment: | Appear to be plumbed to surface | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 456964 Type: WELL API Number: 123-47683 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/26/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 9 Fluid Type: End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 456965 Type: WELL API Number: 123-47684 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/02/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 16 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 456967 Type: WELL API Number: 123-47685 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 01/20/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 314 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 456969 Type: WELL API Number: 123-47687 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/07/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 456972 Type: WELL API Number: 123-47690 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/10/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 87 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 459321 Type: WELL API Number: 123-48804 Status: DG Insp. Status: DG

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder:

Comment: Drilling Status

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/31/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 459322 Type: WELL API Number: 123-48805 Status: DG Insp. Status: DG

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder:

Comment: Drilling Status

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/31/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary

On Wednesday 4/21/21 at approximately 0747hrs, I, Inspector Adam Burns,

Conducted an on-site inspection at D 19-03 of Noble Energy, at

Location ID # 456625 in Weld County, Colorado.

During this inspection the following possible compliance issues were observed:

Trash in multiple locations, needs to be removed for good housekeeping. Comply with Rule

606. With a corrective action date of 4/30/21

See attached photos.

A follow up on this site inspection needs to be conducted to ensure the

compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

burnsa

04/21/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402666883 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5409646 |
| 699103414 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5409641 |