

TEP
Hilton 25-26D
Location # 413865



Location/ no tank battery signage



location

TEP
Hilton 25-26D
Location # 413865



location



location

TEP
Hilton 25-26D
Location # 413865



Lack of stabilization/compaction



TEP
Hilton 25-26D
Location # 413865



Debris

TEP
Hilton 25-26D
Location # 413865



Production tank is open to atmosphere through pipe on top of tank, no Enardo valve, thief hatch is closed.