

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /5B Pad

Location ID: 334466



Photo #3626 from entrance to location.



Photo #3627 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /5B Pad

Location ID: 334466



Photo #3628 No battery sign located at the tank battery.



Photo #3629 Location lack stabilization.



Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /5B Pad

Location ID: 334466

Network time is not synchronized
Local: Apr 26, 2021 at 1:53:56 PM MDT



Photo #3630 Location lacks stabilization.

Network time is not synchronized
Local: Apr 26, 2021 at 1:54:18 PM MDT



Photo #3631 Location lacks stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /5B Pad

Location ID: 334466



Photo #3632 No form of tracking BMP at entrance to location.