

# Inspection Photos

API: 071-07672

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/27/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07672 | Date: 4/27/2021

## Inspection Photos



**Photo 1.** Facing southwest toward the location. The cut slope is stabilized and vegetated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07672 | Date: 4/27/2021

## Inspection Photos



04.27.2021

**Photo 2.** Well sign posted at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07672 | Date: 4/27/2021



## Inspection Photos



**Photo 3.** Facing toward the well which is enclosed by the shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07672 | Date: 4/27/2021