



PHOTO: VIEW OF POSITIVELY LOCATED AS-DRILLED WELL CASING CAMERA ANGLE: NORTHERLY



PHOTO: VIEW OF POSITIVELY LOCATED AS-DRILLED WELL CASING CAMERA ANGLE: EASTERLY

GREAT WESTERN OPERATING COMPANY

SUPERS #1
SW 1/4 NW 1/4, SECTION 32, T1S, R66W, 6th P.M.
ADAMS COUNTY, COLORADO



UELS, LLC
 Corporate Office * 85 South 200 East
 Vernal, UT 84078 * (435) 789-1017

TAKEN BY	O.R.	04-22-21	
DRAWN BY	C.IVIE	04-23-21	
LOCATION PHOTOS			PHOTO 1



PHOTO: VIEW OF POSITIVELY LOCATED AS-DRILLED WELL CASING CAMERA ANGLE: SOUTHERLY



PHOTO: VIEW OF POSITIVELY LOCATED AS-DRILLED WELL CASING CAMERA ANGLE: WESTERLY

GREAT WESTERN OPERATING COMPANY

SUPERS #1
SW 1/4 NW 1/4, SECTION 32, T1S, R66W, 6th P.M.
ADAMS COUNTY, COLORADO



UELS, LLC
 Corporate Office * 85 South 200 East
 Vernal, UT 84078 * (435) 789-1017

TAKEN BY	O.R.	04-22-21	
DRAWN BY	C.IVIE	04-23-21	
LOCATION PHOTOS			PHOTO 2



PHOTO: VIEW OF POSITIVELY LOCATED AS-DRILLED WELL CASING

CAMERA ANGLE: ABOVE

GREAT WESTERN OPERATING COMPANY

SUPERS #1
SW 1/4 NW 1/4, SECTION 32, T1S, R66W, 6th P.M.
ADAMS COUNTY, COLORADO

UELS, LLC

Corporate Office * 85 South 200 East
 Vernal, UT 84078 * (435) 789-1017

TAKEN BY	O.R.	04-22-21	
DRAWN BY	C.IVIE	04-23-21	
LOCATION PHOTOS			PHOTO 3

