

Inspection Photos
Location Name: Irish Pad N/A
Location ID: 450827



Photo 1: Location Sign



Photo 2: Location



Inspection Photos
Location Name: Irish Pad N/A
Location ID: 450827



Photo 3: No contents/volume displayed



Photo 4: No contents/volume displayed



Inspection Photos
Location Name: Irish Pad N/A
Location ID: 450827




Photo 5: No contents/volume displayed



Photo 6: No NFPA placard

Inspection Photos
Location Name: Irish Pad N/A
Location ID: 450827



Photo 7: No NFPA placard



Photo 8: No contents/volume displayed



Inspection Photos
Location Name: Irish Pad N/A
Location ID: 450827



Photo 9: No contents/volume displayed



Photo 10: No contents/volume displayed



Inspection Photos
Location Name: Irish Pad N/A
Location ID: 450827



Photo 11: No bird protector