

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 1 Tank Battery Sign



Photo 2 Unused equipment and debris near compressor building



Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 3 Overview of compressor building, unused AST and debris. Cattle panels at eastern edge of excavation.



Photo 4 Eastern edge of excavation, looking west

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 5 Southeast corner of eastern excavation, looking north



Photo 6 Southwest corner of eastern excavation, looking north



Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 7 Southeast corner of eastern excavation, looking east



Photo 8 Debris on western end of location

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 9 Debris on southwest corner of location



Photo 10 View of western excavation, looking west



Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 11 Northeast corner of western excavation, looking southwest

