

API 05-123-08777 Spill ID: 479617



Inspection Photos
Location Name: Jillson A #1 Tank Battery
API 05-123-08777 Spill ID: 479617



Photo 3 Viewing well along access road, looking north.



Photo 4 Tank Battery Sign



Inspection Photos
Location Name: Jillson A #1 Tank Battery
API 05-123-08777 Spill ID: 479617



Photo 5 Partially buried produced water tank.



Photo 6 Partially buried produced water tank netting.

Inspection Photos
Location Name: Jillson A #1 Tank Battery
API 05-123-08777 Spill ID: 479617



Photo 7 Compressor building

