

Inspection Photos
Location Name: Longmont Farms #5
API 05-123-13222 Spill ID 479267



Photo 1 Well sign.



Photo 2 South side of excavation with cattle panels

Inspection Photos
Location Name: Longmont Farms #5
API 05-123-13222 Spill ID 479267



Photo 3 View of flowline repair.



Photo 4 West side of excavation, looking east



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Longmont Farms #5
API 05-123-13222 Spill ID 479267



Photo 5 East side of excavation, looking west.



Photo 6 Stockpile on location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Longmont Farms #5
API 05-123-13222 Spill ID 479267



Photo 6 Southeast corner of excavation looking northwest.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources