

# Inspection Photos

4/16/2021

Operator: TEP ROCKY MOUNTAIN LLC #  
96850

Location ID: 383329  
Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850  
Location ID: 383329



**Photo 1:** Photo taken from the south end of the production area, facing west. Photos 1-4 provide an overview of the production areas from west, north, northeast to southeast.



**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850  
Location ID: 383329



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1. Refer to Inspection #699802891 for corrective actions regarding stormwater.





## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 383329



**Photo 5:** Photo taken from the eastern interim areas of the Location, facing north. Photo shows reclamation of interim areas is not progressing towards 1003 standards.



**Photo 6:** See comments under photo 5.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 383329



**Photo 7:** Photo taken from the east end of the Location, facing southwest. Photo shows reclamation of interim areas is not progressing towards 1003 standards.



**Photo 8:** Photo taken from the east end of the Location, facing northwest. See comments under photo 7.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 383329



**Photo 9:** Close up of the interim areas soil surface



**Photo 10:** Photo to compare/contrast interim areas to the adjacent reference.