

# Inspection Photos

4/27/2021

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 315237

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Operator Name: RIO MESA RESOURCES INC - 74740**  
**Location ID: 315237**



**Photo 1:** Photo taken from the east end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north. Photo shows additional reclamation has been performed, however, compaction issues are apparent on the Location, and stormwater control measures have not been implemented.



**Photo 2:** See comments under photo 1.

## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



**Photo 5:** Photo shows the soil surface of the Location. Location has been regraded and soils replaced. However, Reclamation Specialist was unable to find any evidence that revegetation (seeding) activities have been performed per Rules and Corrective actions. Photo also shows that stabilization control measures have not been implemented per corrective actions.



**Photo 6:** Photo taken from the western end of the Location, facing northeast. Photo shows pipe debris that has not been removed from the Location.



**Inspection Photos**  
**Operator Name: RIO MESA RESOURCES INC - 74740**  
**Location ID: 315237**



**Photo 7:** Photo taken from the western areas of the Location, facing southeast. Photo shows examples of the Location where compaction issues area apparent as the surface.



**Photo 8:** Photo taken from the eastern areas of the Location, facing southeast. Photo shows examples of the Location where compaction issues area apparent as the surface.



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



**Photo 9:** Reclamation Specialist dug a test pit on the Location to determine compliance with compaction alleviation requirements; comaction issues were observed in the top 4-5 inches of the soil; it is unclear if compaction alleviation has been performed per COGCC Rules.



**Photo 10:** See comments under photo 9.



## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



**Photo 11:** Photo taken from the northwestern corner of the Location, facing east. Photo shows requires stormwater and erosion control measures have not been implemented on the Location per Rules, and corrective actions.



**Photo 12:** Photo taken from the northwestern corner of the Location, facing south. Photo shows requires stormwater and erosion control measures have not been implemented on the Location per Rules, and corrective actions.