

Final Reclamation Inspection

April 21, 2021

Operator: MALLARD EXPLORATION LLC- #10670

Location ID: 464461

Inspection Document #: 697502802

Weld County, CO

SWSE Section 9 T8N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Duclair /Pad
Location ID: 464461



Photo 1. Photo taken from the proposed location, facing North. Photo illustrates location has not been constructed at the proposed well location based off field observations.