

Inspection Photos

Location Name: Facility #4 North Consolidation

Spill ID: 463820 & 477605 Remediation #13446



COGCC Environmental Inspection
40.1023, -104.94472, 4919.3ft, 281°
04/27/2021 01:21:23 PM

Photo 1 – Spill area. No work done since previous inspection.



COGCC Environmental Inspection
40.10231, -104.94472, 4914.5ft, 258°
04/27/2021 01:21:27 PM

Photo 2 – Spill area. No work done since previous inspection.