

Inspection Photos
Operator: Logos Operating
API: 067-07946
Date: 4/22/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, smooth brome, and rubber rabbitbrush.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with sagebrush shrubland, squirreltail, Indian ricegrass, and mat penstemon.