Location Name: DUDE CANYON 22-32, 4-29-21, 4-29-21, API #: 071-08257, Insp. #:695104334

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

PHOTO 3: AREA OF IMPACTED SOIL NEAR TR WELLHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002..(2).D. CA DATE 5-6-21

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

PHOTO 4: AREA OF IMPACTED SOIL NEAR TR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002..(2).D. CA DATE 5-6-21

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

PHOTO 5: UNNECESSARY EQUIPMENT STORED ON LOCATION. COMPLY WITH RULE 606, REMOVE UNNECESSARY EQUIPMENT. CA DATE 5-29-21.

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

PHOTO 6: TRASH ALL OVER LOCATION (APPEARS TO BE COMING FROM UNNECESSARY EQUIPMENT). REMOVE TRASH, COMPLY WITH RULE 606. 5-6-21.

PHOTO 7: TRASH ALL OVER LOCATION (APPEARS TO BE COMING FROM UNNECESSARY EQUIPMENT). REMOVE TRASH, COMPLY WITH RULE 606. 5-6-21.

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

PHOTO 8: TRASH ALL OVER LOCATION (APPEARS TO BE COMING FROM UNNECESSARY EQUIPMENT). REMOVE TRASH, COMPLY WITH RULE 606. 5-6-21.

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

PHOTO 9: TRASH ALL OVER LOCATION (APPEARS TO BE COMING FROM UNNECESSARY EQUIPMENT). REMOVE TRASH, COMPLY WITH RULE 606. 5-6-21.

PHOTO 10: TR WELL IS BEING OPERATED UNDER A PARTIAL VACUUM. FORM 4 APPROVED DOC#402103829

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

PHOTO 11: OILY WASTE MIXED WITH WATER IN PRIME MOVER ENGINE SKID. COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181 . CA DATE 5-6-21.