

Inspection Photos

4/27/2021

Operator: C & J FIELD SERVICES - 10027

Location ID: 311815

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: C & J FIELD SERVICES - 10027
Location ID: 311815



Photo 1: Photo of sign and wellhead.



Photo 2: Photo taken from the flowline riser on the North end of the Location. Integrity issues were observed on the flowline/flowline system. Additionally, flowline equipment does not appear to have been registered/mapped pursuant to the 1101 Rules.

Inspection Photos
Operator Name: C & J FIELD SERVICES - 10027
Location ID: 311815



Photo 3: See comments under photo 2.



Photo 4: Photo taken from the north end of the Location, facing south. Photo shows Halogeton establishment that was observed on the interim and production areas of the Location.

Inspection Photos

Operator Name: C & J FIELD SERVICES - 10027

Location ID: 311815



Photo 5: See comments under photo 4. Yellowed plants in lower area of photos is Halogeton that had established in the 2020 growing season. Smaller green vegetation seen in photo is germinating Halogeton plants, as well as other undesirable weedy plant species.