

# Inspection Photos

4/27/2021

Operator: C & J FIELD SERVICES - 10027

Location ID: 311812

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: C & J FIELD SERVICES - 10027  
Location ID: 311812



**Photo 1:** Photo of sign and wellhead. Photo also shows Halogeton and undesirable weedy plant establishment that was observed on the interim and production areas of the Location.

**Photo 2:** Photo taken from the west end of the Location, facing northeast. Photo shows Halogeton and undesirable weedy plant establishment that was observed on the interim and production areas of the Location.

Inspection Photos  
Operator Name: C & J FIELD SERVICES - 10027  
Location ID: 311812



**Photo 3:** Photo taken from the west end of the Location, facing southeast. Photo shows Halogeton and undesirable weedy plant establishment that was observed on the interim and production areas of the Location.



**Photo 4:** Photo taken from the flowline riser on the north end of the Location. Integrity issues (corrosion/leaking) were observed on the flowline/flowline system.

Inspection Photos  
Operator Name: C & J FIELD SERVICES - 10027  
Location ID: 311812



**Photo 5:** See comments under photo 4.



**Photo 6:** See comments under photo 4.

Inspection Photos  
Operator Name: C & J FIELD SERVICES - 10027  
Location ID: 311812



**Photo 7:** Photo taken from the flowline riser on the south end of the Location, facing north. Integrity issues (corrosion/leaking) were observed on the flowline/flowline system.

**Photo 8:** See comments under photo 7.