

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402676538  
Receive Date:  
05/03/2021

Report taken by:  
PETER GINTAUTAS

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	<b>Phone Numbers</b>
Address: <u>1775 SHERMAN STREET - STE 3000</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80203</u>
Contact Person: <u>Karen Olson</u>	Email: <u>COGCCSpillRemediation@pdce.com</u>	
		Phone: <u>(303) 860-5800</u>
		Mobile: <u>( )</u>

PROJECT, PURPOSE & SITE INFORMATION

**PROJECT INFORMATION**

Remediation Project #: 15233 Initial Form 27 Document #: 402301827

**PURPOSE INFORMATION**

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input type="checkbox"/> Other _____

**SITE INFORMATION** Y Multiple Facilities ( in accordance with Rule 909.c. )

Facility Type: <u>LOCATION</u>	Facility ID: <u>311414</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>SHIVERS-62N66W 29NENE</u>	Latitude: <u>40.115108</u>	Longitude: <u>-104.793480</u>	
** correct Lat/Long if needed: Latitude: <u>40.112399</u>		Longitude: <u>-104.797044</u>	
QtrQtr: <u>NENE</u>	Sec: <u>29</u>	Twp: <u>2N</u>	Range: <u>66W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>471003</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>Shivers 1 &amp; 14-29</u>	Latitude: <u>40.112399</u>	Longitude: <u>-104.797044</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NENE</u>	Sec: <u>29</u>	Twp: <u>2N</u>	Range: <u>66W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

**SITE CONDITIONS**

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Cropland

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

**Other Potential Receptors within 1/4 mile**

A riverine is located 60 feet north, a pond is located 420 feet southeast, and freshwater wetlands are located 520 feet northeast. Livestock is located 405 feet northeast and a residence is located 1,160 feet northeast. An irrigation well is located 940 feet northwest.

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |   |  |  |
|---|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input type="checkbox"/> Produced Water       | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input checked="" type="checkbox"/> Oil       | <input type="checkbox"/> Tank Bottoms                |  |
| <input type="checkbox"/> Condensate           | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids      | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings       | <input type="checkbox"/> Spent Filters               |  |
|   | <input type="checkbox"/> Pit Bottoms                 |  |
|   | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	Refer to Figure 1 and Table 1	Site investigation

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Historic hydrocarbon impacts were discovered below former tank battery infrastructure following a post-reclamation site investigation.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

On January 17 and March 3, 2020, 15 soil borings (FSB01 – FSB15) were advanced to depths ranging between 7.5 feet and 11 feet below ground surface (bgs) using a hand auger. Soil encountered in the soil borings was field screened for volatile organic compound (VOC) concentrations using a photoionization detector (PID). Soil samples were collected from the vertical intervals which exhibited elevated field-measured VOC concentrations. Twenty-four soil samples were submitted for laboratory analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, and total petroleum hydrocarbons (TPH) – gasoline range organics (GRO) by Environmental Protection Agency (EPA) Method 8260B, TPH – diesel range organics (DRO) by EPA Method 8015. Analytical results indicated that TPH concentrations were in exceedance of COGCC Table 910-1 standards in six soil boring locations.

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Groundwater was encountered during the investigations at approximately 8 feet bgs. A groundwater sample will be collected from the excavation following the completion of source mass removal activities.

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

## Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 24  
Number of soil samples exceeding 910-1 9  
Was the areal and vertical extent of soil contamination delineated? No  
Approximate areal extent (square feet) 4877

### NA / ND

-- Highest concentration of TPH (mg/kg) 3190  
NA Highest concentration of SAR             
BTEX > 910-1 No  
Vertical Extent > 910-1 (in feet) 7

### Groundwater

Number of groundwater samples collected 7  
Was extent of groundwater contaminated delineated? Yes  
Depth to groundwater (below ground surface, in feet) 8'  
Number of groundwater monitoring wells installed 7  
Number of groundwater samples exceeding 910-1 0

ND Highest concentration of Benzene (µg/l)             
ND Highest concentration of Toluene (µg/l)             
-- Highest concentration of Ethylbenzene (µg/l) 1.3  
ND Highest concentration of Xylene (µg/l)             
NA Highest concentration of Methane (mg/l)           

### Surface Water

0 Number of surface water samples collected  
           Number of surface water samples exceeding 910-1  
If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)            Volume of liquid waste (barrels)           

Is further site investigation required?

Additional investigation activities will be conducted to determine the vertical and lateral extents of remaining hydrocarbon impacts in soil. A groundwater assessment will also be conducted following the evaluation of initial groundwater data.

# REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No \_\_\_\_\_

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Based on the analytical results collected during the site investigation conducted in the first quarter 2020, remaining hydrocarbon impacted material will be removed via mechanical excavation and transported to a disposal facility under PDC waste manifests. Source mass removal activities are scheduled to be completed following the 2020 agricultural season.

## REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

On March 31, 2020, seven temporary monitoring wells (BH01-BH07) were advanced via hand auger to conduct an initial groundwater assessment. Following the installation, monitoring wells were developed, surveyed, and subsequently sampled. Seven groundwater samples were submitted to Summit Scientific Laboratories for analysis of benzene, toluene, ethylbenzene, and total xylenes (BTEX) by EPA Method 8260B. Analytical results indicated that BTEX concentrations were below COGCC Table 910-1 groundwater standards in all seven sample locations. Based on the analytical results, monitored natural attenuation (MNA) will be the selected remediation strategy for the first quarter 2020 and continue as the selected remediation strategy for the second quarter 2021.

## Soil Remediation Summary

### In Situ

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

### Ex Situ

- \_\_\_\_\_ Excavate and offsite disposal
- \_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_
- \_\_\_\_\_ Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_
- \_\_\_\_\_ Excavate and onsite remediation
- \_\_\_\_\_ Land Treatment
- \_\_\_\_\_ Bioremediation (or enhanced bioremediation)
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- Yes \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater monitoring will continue on a quarterly basis at the seven site temporary monitoring wells (BH01 - BH07). Due to the location of the former tank battery and active farming activities, the temporary monitoring wells are installed via hand auger on a quarterly basis and subsequently abandoned following sampling activities. A GPS point is collected from each temporary monitoring well location to ensure the groundwater sample locations remain consistent between quarters. Groundwater samples will be submitted for laboratory analysis of benzene, toluene, ethylbenzene, and total xylenes (BTEX), naphthalene, 1,2,4-trimethylbenzene, and 1,3,5-trimethylbenzene by EPA Method 8260B in accordance with Table 915-1. In addition, site-specific inorganic parameters, including total dissolved solids (TDS), chloride, and sulfate, will be evaluated at the source, up-and down-gradient monitoring wells during the second quarter 2021. Contingent on analytical results, inorganic parameter analysis will be discontinued after one sampling event.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

Frequency:  Quarterly  Semi-Annually  Annually  Other \_\_\_\_\_

Report Type:  Groundwater Monitoring  Land Treatment Progress Report  O&M Report

Other \_\_\_\_\_

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

Do all soils meet Table 910-1 standards? \_\_\_\_\_

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? \_\_\_\_\_

Does Groundwater meet Table 910-1 standards? \_\_\_\_\_

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Following the completion of remediation activities, the location will be reclaimed in accordance with the COGCC 1000 Series.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim?  Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

# IMPLEMENTATION SCHEDULE

## PRIOR DATES

Date of Surface Owner notification/consultation, if required. 01/24/2020

Actual Spill or Release date, if known. \_\_\_\_\_

## SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 01/17/2020

Date of commencement of Site Investigation. 01/17/2020

Date of completion of Site Investigation. \_\_\_\_\_

## REMEDIAL ACTION DATES

Date of commencement of Remediation. \_\_\_\_\_

Date of completion of Remediation. \_\_\_\_\_

## SITE RECLAMATION DATES

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

## OPERATOR COMMENT

This Supplemental Form 27 was submitted to summarize quarterly groundwater monitoring activities and analytical results collected during the first quarter 2021 at the Shivers 1 & 41-29 location.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Karen Olson

Title: Senior Program Manager

Submit Date: 05/03/2021

Email: COGCCSpillRemediation@pdce.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: PETER GINTAUTAS

Date: 05/03/2021

Remediation Project Number: 15233

## Condition of Approval

### COA Type

### Description

<u>COA Type</u>	<u>Description</u>
0 COA	

## Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

### Att Doc Num

### Name

402676538	FORM 27-SUPPLEMENTAL-SUBMITTED
402676546	MONITORING REPORT

Total Attach: 2 Files

## General Comments

### User Group

### Comment

### Comment Date

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)