

# Inspection Photos

API: 071-08256

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/30/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08256 | Date: 4/30/2021

## Inspection Photos



**Photo 1.** Facing west toward main road. The road has been regraded and repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08256 | Date: 4/30/2021

## Inspection Photos



**Photo 2.** Areas of erosion and rutting have been repaired along the main road ascending to the hillside to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08256 | Date: 4/30/2021

## Inspection Photos



**Photo 3.** Areas of erosion and rutting have been repaired along the main road ascending to the hillside to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08256 | Date: 4/30/2021

## Inspection Photos



**Photo 4.** Facing at the location. Well sign installed at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08256 | Date: 4/30/2021

## Inspection Photos



**Photo 5.** Stained soil at the engine skid has been cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08256 | Date: 4/30/2021