



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

A29D pad
Inspection: 701500561



39.85251, -108.31312, 6186.7ft, 4°
04/30/2021 02:50:50 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Location.

A29D pad
Inspection: 701500561



39.85322, -108.31266, 6199.4ft, 26°
04/30/2021 02:53:45 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separators.

A29D pad
Inspection: 701500561



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tanks.

A29D pad
Inspection: 701500561