

Inspection Photos
Location Name: McCallum Unit 12
Location ID: 324587



Photo 1. Overview of location taken facing northeast.



Photo 2. No bradenhead access apparent.

Inspection Photos
Location Name: McCallum Unit 12
Location ID: 324587



Photo 3. Stained soil on location.



Photo 4. Stained soil on location.