

Inspection Photos
Location Name: McCallum 154
Location ID: 324722



Photo 1. Overview of location taken facing southwest.



Photo 2. No bradenhead access apparent. Stained soil at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources