

Construction and Stormwater Inspection

April 27, 2021

Operator: NOBLE ENERGY INC- #100322

Location ID: 477361

Inspection Document #: 697502814

Weld County, CO

NENE Section 30 T6N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: A30-01 /Pad
Location ID: 477361



Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates Operator has installed a vehicle tracking device BMP. At the time of this inspection, no vehicle track out issues were observed.

Inspection Photos
Location Name: A30-01 /Pad
Location ID: 477361



Photo 2. Photo taken from the northeastern location, facing South. Photo illustrates Operator has installed surface roughening and filter wattle BMPs around the entire perimeter of location. Topsoil is being salvaged and stored along the southern and western perimeter of the location.



Inspection Photos
Location Name: A30-01 /Pad
Location ID: 477361



Photo 3. Photo taken from the northeastern location, facing West. See comments under Photo 2.

Inspection Photos
Location Name: A30-01 /Pad
Location ID: 477361



Photo 4. Photo taken from the northern location, facing West. Operator indicated that ~17.5" of topsoil was being salvaged.

Inspection Photos
Location Name: A30-01 /Pad
Location ID: 477361



Photo 5. Photo taken from the northern location, facing Southwest. See comments under Photo 4.

Inspection Photos
Location Name: A30-01 /Pad
Location ID: 477361



Photo 6. Photo taken from the central location, facing Southwest. See comments under Photo 4.