

Inspection Photos

4/30/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335145

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335145



Photo 1: Photo taken from the northeast corner of the Location, facing northwest. Previous inspection observed that control measures to stabilize/protect unpaved areas. Photo shows Operator has regraded the production areas, however control measures to stabilize/protect pad and prevent offsite sediment transport during wet conditions remain missing or insufficient.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335145



20210430

Photo 2: Photo taken from the northeast corner of the Location, facing south. Previous inspection observed that control measures to stabilize/protect unpaved areas. Photo shows Operator has regraded the production areas, however control measures to stabilize/protect pad and prevent offsite sediment transport during wet conditions remain missing or insufficient.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335145



Photo 3: Photo taken from the south end of the Location, facing southwest. Photo shows Operator has installed a sediment trap and slope drain; It is unclear at time of inspection if control measures are adequate or sufficient for the site's conditions.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335145



Photo 4: Photo of the slope drain. See comments under photo 3.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335145



Photo 5 Photo of the slope drain outlet. See comments under photo 3.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335145



Photo 6: Photo taken from the slopes on the west end of the Location. Photo shows erosion degradation remains evident on the slopes; control measures to stabilize/protect slopes remain missing or insufficient.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335145



Photo 7: See comments under photo 6.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335145



Photo 8: See comments under photo 6.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources