

Inspection Photos

Loc#335385

Operator: Caerus

Insp#:692403349

Insp Date: 4/29/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

April 29, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#335385



Photo#2:
Interim area.



Photo#3:
Overview of Location to South .

April 29, 2021